

March 2007


## Technical Bulletin - Firmware Identification Trimble Ag132 and Trimble Ag332

### Procedure to identifying the Firmware Version

OmniSTAR requires your firmware on your GPS receiver to be upgraded, in order to maintain a high standard of service from your GPS receiver. (Please note this procedure is different from the Frequency Changeover to OCSAT).

Both the Trimble AgGPS 132 and the AgGPS 332 display their firmware version in the same menu screen.

From the home screen.




1. Press the RIGHT arrow  until the STATUS screen appears.



**This document is for informational purposes only and is not a legally binding agreement or offer. Trimble makes no warranties and assumes no obligations or liabilities hereunder.**

2. Press the DOWN  arrow ONCE.



3. Press the RIGHT arrow  until the RECEIVER STATUS screen appears.



4. Press the DOWN button  until the VERSION screen appears.



5. Version 3.00 or above is suitable firmware.

**Please contact your nearest OmniSTAR branch below should you require any assistance.**

North, Central & South America	Asia Pacific, China & India	Europe / CIS & Middle East	Africa
+1-713-785-5850	+61-8-9322-5295	+31-70-317-0900	+27 (0) 21 527 8950
gps@omnistar.com	support@omnistar.com.au	support@omnistar.nl	technical.ossa@omnistar.com